

Table 1

List of air accidents at or near Shoreham Airport as of 2024			
4 October 1910	unreg	Harold H. Piffard No.2 "Hummingbird" Biplane crashed near Sussex Pad whilst being filmed	https://aviation-safety.net/wikibase/233094
29 June 1913	unreg	Avro 500 Type E Military prototype Biplane Stalled crashed into garden N Salts Farm at Shoreham. BF. Pilot survived but succumbed to fire injuries 1k.	https://aviation-safety.net/wikibase/218041
26 April 1914	Unreg	Lee-Richards Annular Monoplane No.2 prototype crash at Shoreham	https://aviation-safety.net/wikibase/238437
4 May 1914	27	Sopwith School Tractor Biplane of RNAS Shoreham. F/L and o/t nr base.	
12 May 1914	36	Deperdussin Monoplane of RNAS Shoreham. Crashed – NFD	
12 June 1914		BE2C of Royal Aircraft Factory Farnborough. Crashed after t/o fm Shoreham. BF. 1k.	
23 June 1914		Bleriot of Gosport. EF on approach to Shoreham, stalled. 1k.	
10 August 1914	889	Avro 504 SP. Crashed Shoreham on delivery.	
4 February 1915	unreg	Maurice Farman MF.20 of 3 RFC Sqn Shoreham. Dived in Sussex Pad pub, Lancing. 1k.	https://aviation-safety.net/wikibase/218547
23 June 1915	unreg	Bleriot X1 RFC Gosport crashed at Shoreham 1k	https://aviation-safety.net/wikibase/218601
12 July 1915		BE2.C RFC crashed at Shoreham 1k	https://aviation-safety.net/wikibase/218605
24 September 1915	8107	Maurice Farman MF S.11 Shorthorn of RNAS Shoreham. Crashed base.	
22 May 1917	6581	BE12 of 78 Sqn Shoreham. Collided whilst over Hove with below. 1k.	
22 May 1917	A602	BE12A of 78 Sqn Shoreham. Collided whilst over Hove with above. 1k.	
21 August 1917	A2495	Maurice Farman MF S.11 Shorthorn of 3 TSqn Shoreham. Pilot fell out in dive, crashed Ecclesden Fm, Angmering WS. 1k.	
3 September 1917	A2468	Maurice Farman MF S.11 Shorthorn of 3 TSqn Shoreham. EF, side-slipped and dived in Ham Bridge, Worthing WS. 1k	
6 September 1917	A2501	Maurice Farman MF S.11 Shorthorn of 3 TSqn Shoreham. Side-slipped into R. Adur nr base. 1k.	
11 September 1917	B2018	Maurice Farman MF S.11 Shorthorn of 3 TSqn Shoreham. Propellor broke, crashed in sea off Rustington WS. 1k.	
11 September 1917	B2582	Strutter of 78 Sqn Shoreham. Hit tree ldg nr Bexleyheath K. 1k.	
19 January 1918	B6096	Sopwith Pup of 3 TSqn Shoreham. Controls jammed by pilot's foot, spun in - NFD	
28 January 1918	B9282	Camel of 3 TSqn Shoreham. Stalled fm turn after t/o, spun in. Trainee US pilot 1k.	
8 February 1918	B2385	Camel of 3 TSqn Shoreham. Crashed - NFD	
28 October 1918	D1812	Camel of 204 TDS Eastchurch. Hit hill in fog Thundersbarrow Down 2m N of Shoreham. 1k	
22 May 1919	8482	Fokker DVII of 123 Sqn Shoreham. Wing failed in dive at base. 1k	
18 June 1927		Airco DH9A crashed nr Shoreham	https://www.shorehambysea.com/airco-crash-lancing/
22 August 1928	G-EATU	Avro 504K. Crashed nr Shoreham Cecil Pashley pilot.	https://aviation-safety.net/wikibase/25281
17 July 1930	G-EBKN	Avro 548A modified with inline engine, FL at Shoreham, dismantled	https://aviation-safety.net/wikibase/247081
26 May 1932	K2036	Hawker Fury I of 1 Sqn Tangmere. Collided with K2064 in formation, crashed Buckingham Park nr Shoreham. 1k.	http://aviation-safety.net/wikibase/68710
26 May 1932	K2064	Hawker Fury I of 1 Sqn Tangmere. Collided with K2036, caught fire, abandoned and crashed nr Shoreham.	http://aviation-safety.net/wikibase/68723
11 March 1933	G-AAUO	Robinson Redwing prototype. Crashed on landing at Shoreham	https://aviation-safety.net/wikibase/201681
2 September 1934	G-AATJ	Desoutter I. Crashed Shoreham on takeoff	https://aviation-safety.net/wikibase/201614

List of air accidents at or near Shoreham Airport as of 2024			
23 May 1936	G-ABWL	Gipsy Moth. Crashed Shoreham	https://aviation-safety.net/wikibase/202712
17 August 1937	G-AEEK	de Havilland DH.90 Drogonfly Crashed at Beeding ct Farm 4 miles north of Shoreham	https://aviation-safety.net/wikibase/18778
24 September 1937	G-AALX	Moth 60M. Ditched off Shoreham Harbour. 1k.	https://aviation-safety.net/wikibase/201230
14 April 1939	K4431	Hawker Hart Special of 16 E&RFTS Shoreham. Hit hill in cloud Streat Hill Fm nr Plumpton ES. 1k	
27 June 1939	G-ABBW	Gipsy Moth. Ditched off Shoreham. 1k.	https://aviation-safety.net/wikibase/202357
15 June 1940	N2615	Hurricane I of 43 Sqn Tangmere. Dived in sea during practice attack 5m E of Shoreham.	
19 July 1940	G1+AR	He 111P of III/KG55 GAF Villacoublay Fr. SDF 5m off Shoreham. 5k.	
13 August 1940	5068	Bf 109E of Stab I/JG2 GAF Beaumont-le-Roger Fr. F/L New Salts Fm nr Shoreham. Flown by Oblt. Paul Temme . Hit by Hurricane of No.43 Sqn.	https://aviation-safety.net/wikibase/177454
4 September 1940	3M+AA	Bf 110C of St/ZG2 GAF Toussus-les-Noble Fr. SDF F/L Mill Hill, Shoreham Downs WS	
30 September 1940	X4069	Spitfire IA of 92 Sqn Biggin Hill. SD by 109 and C/L Shoreham	
9 December 1940	R2147	Beaufighter IF of FIU Ford. O/s and skidded into ditch, Shoreham	
18 May 1941	Z2700	Hurricane IIA of 258 Sqn Kenley. Crashed in sea 8 m off Shoreham WS.	
19 June 1941	V5395	Blenheim IV of 59 Sqn Thorney Island. Hit sea avoiding flak on convoy attack, C/L Shoreham.	
14 July 1941	L4752	Lysander II of 7 AACU Shoreham. Crashed Black Down SE of Haslemere SR.	
1 September 1941	AD833	HP Hampden I of 16 OTU Upper Heyford Oxon. Crashed on night approach in fog to Shoreham and hit trees, Lancing College WS. 4k.	
28 July 1942	HL655	Hurricane IIC of 32 Sqn West Malling. Fire in air, spun in nr Shoreham WS	https://aviation-safety.net/wikibase/311300
18 December 1942	R8800	Typhoon IB of 486(NZ) Sqn Tangmere. SD by Do217 10m SE of Shoreham.	
20 January 1943	V8266	Beaufighter Mk IF of 41 Squad. Ford. Crashed in sea 5m S of Shoreham 2k	https://aviation-safety.net/wikibase/262937
11 June 1943	W2725	Walrus I of 277(ASR) Sqn Shoreham. F/L at base and u/c collapsed	
4 August 1943	42-3287	Fortress B-17F of 385 BG USAAF Great Ashfield Suffolk. C/L at Shoreham. 1k.	
12 August 1943	DV731	Wellington IC of 28 OTU satellite Castle Donington Leics. Flak damage on leaflet raid, ditched off Shoreham. 4k	
24 August 1943	41-34703	Marauder B-26C of 323 BG Earls Colne Ess. Crashed at Kingston-by-Sea WS approach Shoreham.	
13 November 1943	JP597	Typhoon IB of 181 Sqn Merston. Ditched off Shoreham	
15 November 1943	BM564	Spitfire VB of 306(Polish) Sqn Heston Middlesex. U/c collapsed Idg at Shoreham	
30 November 1943	BD259	Whitley Mk V attempt to land with single engine, crashed short of runway New Salts Farm, 300 yards south of RAF Shoreham	https://aviation-safety.net/wikibase/302668
11 February 1944	42-31314	Fortress B-17G of 303 BG USAAF Molesworth Hunts.O/s Idg at Shoreham. "Scorchy"	https://aviation-safety.net/wikibase/302666
28 February 1944	P7911	Spitfire Mk Ila F/L crash into wall at Shoreham	https://aviation-safety.net/wikibase/165651
11 April 1944	BF455	Stirling III of 75(NZ) Sqn Newmarket. Flak damage and oofuel on return fm Frankfurt, ditched 3m off Shoreham, rescue by Walrus	https://aviation-safety.net/wikibase/274201
29 April 1944	EN-865	Spitfire VB of 345 (French) Sqn Shoreham. Crashed on Idg at base.	https://aviation-safety.net/wikibase/302644
30 April 1944	MH455	Spitfire IX of 66 Sqn Bognor Regis. EF, No.66 Sqn radiator problems after a dive bombing raid, stalled and crashed near Shoreham as attempted to bale out. 1k PO Hughes	

List of air accidents at or near Shoreham Airport as of 2024			
4 July 1944	42-26137	Thunderbolt P-47D of 373 FG USAAF Woodchurch. EF, belly-landed at Shoreham	https://aviation-safety.net/wikibase/116529
30 July 1944	W3264	Spitfire VB of 345(French) Sqn Shoreham. Taxied into concrete	
6 February 1945	43-37992	B17G Flying Fortress battle damaged forced landing in fields Truleigh Hill, Beeding 4m N of Shoreham. Salvaged	https://aviation-safety.net/wikibase/98202
25 July 1947	G-AIKH	Percival Proctor I. Crashed at Shoreham	
28 February 1949	G-AKRJ	Miles M.14 Hawk Trainer III. Ditched in sea off Shoreham 2k	https://aviation-safety.net/wikibase/71800
18 August 1951	G-AJXS	Auster Autocrat - - burnt out in hangar at Shoreham	
18 September 1951	G-AHCI	Taylorcraft Plus D - burnt out in hangar at Shoreham	https://aviation-safety.net/wikibase/19477
3 November 1951	G-AITO	Miles M.14A Hawk Trainer III. Crashed 2m North of Shoreham.	https://aviation-safety.net/wikibase/233792
7 May 1956	WT328	Canberra B(l)8 of AAEE Boscombe Down Wilts. Flew into sea on altimeter trials 2.5m S of Shoreham. 2k.	https://aviation-safety.net/wikibase/142144
11 May 1956	WP202	Vickers Valiant B1 test flight crashed on railway adjacent Southwick train station 3k	https://aviation-safety.net/wikibase/71801
28 June 1958	G-AHDM	HDM105 Aerovan modified. Stalled on approach and heavy landing at Shoreham	https://aviation-safety.net/wikibase/152103
19 May 1960	XP188	Westland Scout AH1 of Saro. EF, F/L in caravan park, Shoreham.	https://aviation-safety.net/wikibase/64767
26 October 1960	G-AKFX	Miles M65 Gemini 8. Crashed on t/o fm Shoreham.	https://aviation-safety.net/wikibase/66090
12 May 1962	XR942	Wallis WA116 of AAC. Autogyro Taxi-ing accident at Shoreham 2 days after first flight. Reg reallocated	
13 March 1964	G-AKXO	Tiger Moth. Hit tree at 77 Buckingham Rd, Shoreham on on approach to Shoreham. 2k.	https://www.shorehambysea.com/crash-of-a-akxo-march-1964/
11 August 1968	G-ASDB	Druine D.31 Turbulent. Crashed during display to burst a balloon with wing at Shoreham. 1k	https://aviation-safety.net/wikibase/71701
4 September 1971	G-AWUK	Cessna 150. Crashed at Shoreham on TO	https://aviation-safety.net/wikibase/245000
6 June 1972	G-APCL	Piper Apache. Crashed on making asymmetric ldg at Shoreham	https://aviation-safety.net/wikibase/166459
5 August 1975	G-ATKR	Druine D.31 Turbulent. Crashed at Shoreham during airshow	https://aviation-safety.net/wikibase/245162
11 March 1979	G-BEOG	Cessna 182. Hit power station chimney in fog and crashed in oil storage depot at Shoreham. 2k.	https://aviation-safety.net/wikibase/18655
17 June 1979	G-ARLO	Beagle A.61 Terrier 1. F/L in sea off Shoreham.	https://aviation-safety.net/wikibase/18003
11 January 1981	G-AVWZ	Fournier RF-4D . Crashed on t/o fm Shoreham 1k	https://aviation-safety.net/wikibase/245116
19 December 1981	G-BHNG	Piper Aztec. Collided with G-BFRB on t/o fm Shoreham.	https://aviation-safety.net/wikibase/244908
19 December 1981	G-BFRB	Cessna 152. Collided with G-BHNG	https://aviation-safety.net/wikibase/244908
29 May 1982	G-BFRU	Cessna 152. DBR at Shoreham.	https://aviation-safety.net/wikibase/18630
15 October 1982	G-BHVS	Enstrom 28. Heavy ldg at Shoreham.	https://aviation-safety.net/wikibase/155674
9 July 1983	G-AMYP	DH.104 Sea Devon C 20. EF on t/o, crashed into Western river bank at Shoreham. 1k.	https://aviation-safety.net/wikibase/67
23 February 1985	OO-PIF	Piper PA-32 300 Cherokee six Very heavy landing	https://aviation-safety.net/wikibase/181422
25 September 1986	G-AZZS	Piper PA-34-200 Seneca FL at Shoreham - airframe written off.	https://aviation-safety.net/wikibase/181890
29 June 1988	G-BIHW	Aeronca Champ. Stalled on approach and wing hit ground, cartwheeled inverted at Shoreham.	https://aviation-safety.net/wikibase/183192
29 August 1988	G-BHZG	Monnett Sonnerai II Canopy came open after t/o fm field nr Shoreham	https://aviation-safety.net/wikibase/183603
6 November 1992	G-BSHE	Cessna 152. F/L night approach training, crashed into high ground north-east of Shoreham Airport.	https://aviation-safety.net/wikibase/187033

List of air accidents at or near Shoreham Airport as of 2024			
8 August 1995	G-BTKT	Warrior. EF, F/L on approach Shoreham	https://assets.publishing.service.gov.uk/media/5422facb40f0b61346000865/Piper_PA-28-161_Cherokee_Warrior_II_G-BTKT_Addendum_11-95.pdf
2 March 1996	G-AXOI	Jodel D.9 Bebe. EF, dived in to field on Idg at Shoreham. 1k	https://aviation-safety.net/wikibase/71806
31 May 1996	G-BJBV	Piper PA-28 Cherokee Warrior crashed landed at Shoreham	https://aviation-safety.net/wikibase/188092
28 December 1997	G-BFZU	Aerobat. Crashed on Idg at Shoreham.	
21 September 1999	G-BXUP	Schweitzer 300. Lost control hovering and hit river bank at Shoreham	
7 October 1999	G-BTGR	Cessna 152. Lost in bad weather, F/L and o/t 3m NE of Shoreham	
7 May 2000	G-BSZT	Piper PA-28-161 Cherokee Warrior II failed TO crash in ditch at Shoreham	https://assets.publishing.service.gov.uk/media/5f58d95e8fa8f5106d156346/Piper_PA-28-161_Cherokee_Warrior_II_G-BSZT_03-19.pdf
2 April 2001	G-OMAR	Piper PA-34 Seneca. Out of fuel hitting roof of house in West St Shoreham	https://aviation-safety.net/wikibase/33356
15 September 2007	G-HURR	Hurricane IIB. Crashed 1m NW of Shoreham (nr Lancing College) airfield during airshow. 1k	https://aviation-safety.net/wikibase/58887
17 October 2008	G-SBUT	Robinson R22. Crashed at Shoreham on pilots first solo	https://aviation-safety.net/wikibase/191002
22 August 2010	G-IZII	Marganski Swift S-1. Display at airshow, stalled fm turn crash at Shoreham.	https://aviation-safety.net/wikibase/76463
4 July 2011	G-RVGC	Vans RV6A. Mid-air collision with Diamond Star G-CEZR in Shoreham circuit, crashed Adur Recreation Ground on Brighton Rd.. 1k.	https://aviation-safety.net/wikibase/137126
21 July 2012	G-TLET	Piper PA 28 Cherokee Warrior II. Lost power after t/o fm Shoreham, F/L and hit fence and hedge.	https://aviation-safety.net/wikibase/179593
29 September 2012	G-ETOJ	Rotosport UK Calidus gyrocopter. Over-rotated, rotor struck ground on TO Crashed at Shoreham	https://aviation-safety.net/wikibase/149343
22 August 2015	G-BXFI	Hunter T7. Crashed fm during aeobatics at airshow crashed on A27 N of Shoreham. 11k on ground.	https://aviation-safety.net/wikibase/178886
18 July 2016	G-AXLZ	Piper L-18 Super Cub. Crashed on t/o fm Shoreham, in helo wake turbulence.	https://aviation-safety.net/wikibase/188734
20 June 2017	G-ATVO	Piper PA-28 Cherokee. EF after t/o fm Shoreham, ditched off beach	https://aviation-safety.net/wikibase/194467
16 February 2018	G-WARZ	G-WARZ. Warrior. Ground collision with G-WARY (survived) Brighton City (Shoreham).	